

Table 7-1
Findings of Suitability to Transfer
First CERFA Parcel Transfer
Summary of Asbestos Containing Building Survey
Fort McClellan, Alabama

Page 1 of 6

Building Number	Year Built	Description	Description & Location of ACM	Condition
141	1937	Company Headquarters Building	Friable, hand formed, asbestos containing insulation compound applied to fittings of water pipes in the basement and throughout the building.	Good
			Friable insulation containing asbestos found on the straight runs of a small section of pipe in the basement area and in a restroom on the 2 nd floor.	Good
			Non-friable asbestos containing 9x9 inch vinyl floor tile found in a single office	Good
143	1930	Administration General Purpose	Friable, hand formed, asbestos containing insulation compound applied to fittings of water pipes in the basement and throughout the building.	Good
			Friable insulation containing asbestos found on the straight runs in various locations in the basement area and 2nd floor restroom	Good
			Aircells type insulation is visible on approximately 20 linear feet of pipe above the drop ceiling on the 2 nd floor.	Good to Fair
			Non-friable asbestos containing 9x9-inch vinyl floor tile found in a single office located in the basement and 12x12-floor tile and mastic found throughout the building.	Good
202	1957	Storage Group Installation	Non-friable presumed asbestos containing 12x12 inch floor tile, mastics and transite piping	Good
204	1954	Dispatch Building	Non-friable presumed asbestos containing 12x12 inch floor tile, mastics and transite siding found on the exterior walls of the building	Good

Table 7-1
Findings of Suitability to Transfer
First CERFA Parcel Transfer
Summary of Asbestos Containing Building Survey
Fort McClellan, Alabama

Page 2 of 6

Building Number	Year Built	Description	Description & Location of ACM	Condition
207	1957	Flammable Material Storage Installation	Non-friable presumed asbestos containing 12x12- inch floor tile and mastics.	Good
211	1960	Entomology Facility	Non-friable presumed asbestos containing 12x12-inch floor tile, mastics.	Good
214	1965	Engineering/Housing Maintenance	Non-friable presumed asbestos containing transite piping.	Good
215	1955	Engineering/Housing Maintenance	Friable, white, chalky insulation and a paper type insulation in the building.	Good
			Non-friable presumed asbestos containing 9x9 inch vinyl floor tiles and transite panels found throughout the building.	Good
698	1941	Administration General Purpose	Non-friable presumed asbestos containing 12x12 inch vinyl floor tile and mastics.	Good
810	1941	General Installation Building	Friable white, air-cell type asbestos containing material found on 12-inch pipe roof vent.	Good/Fair
			Non-friable presumed asbestos containing transite panels found on exterior walls; 12x12-inch floor tile and black, presumed asbestos containing mastics below vinyl floor tiles.	Good
811	1941	General Installation Building	Friable white, air-cell type asbestos containing material found on 12-inch pipe roof vents.	Good/Fair
			Non-friable presumed asbestos containing transite panels found on exterior walls; 12x12 inch floor tile and black, presumed asbestos containing mastics below vinyl floor tiles .	Good

Table 7-1
Findings of Suitability to Transfer
First CERFA Parcel Transfer
Summary of Asbestos Containing Building Survey
Fort McClellan, Alabama
Page 3 of 6

Building Number	Year Built	Description	Description & Location of ACM	Condition
812	1941	General Installation Building	Friable white, air-cell type asbestos containing material found on 12-inch pipe roof vents. Non-friable black, presumed asbestos containing mastics below vinyl floor tiles.	Good/Fair Good
837	1940	Annual Training Enlisted Barracks	Non-friable presumed asbestos containing 12x12 inch floor tile and mastic	Good
888	1942	Maintenance Storage	Non-friable presumed asbestos containing 12x12 inch vinyl floor tile and mastics.	Good
900	1917	Unaccompanied Office Quarters Transient	Non-friable presumed asbestos containing 12x12 inch vinyl floor tile and mastics.	Good
916	1941	Annual Training Enlisted Barracks	A friable, hand formed, asbestos containing insulation compound is applied to the fittings and a cementitious asbestos containing material is found on straight runs of pipes, located within, outside and under the building. Non-friable assumed asbestos containing vinyl floor tiles in 12x12 inch size, and black, asbestos containing mastics are present below vinyl floor tiles.	Good to Poor Good
917	1941	Annual Training Enlisted Barracks	A white, friable, asbestos containing TSI is applied to hot water tanks in the building A friable, hand formed, asbestos containing insulation compound is applied to the fittings and a cementitious asbestos containing material is found on straight runs of pipes, located within, outside and under the building Non-friable assumed asbestos containing vinyl floor tiles in 12x12 inch size, and black, asbestos containing mastics are present below vinyl floor tiles.	Good Good to Poor Good
918	1941	Annual Training Enlisted Barracks	A friable, hand formed, asbestos containing insulation compound is applied to the fittings and a cementitious asbestos containing material is found on straight runs of pipes, located within, outside and under the building	Good to Poor

Table 7-1
Findings of Suitability to Transfer
First CERFA Parcel Transfer
Summary of Asbestos Containing Building Survey
Fort McClellan, Alabama

Page 4 of 6

Building Number	Year Built	Description	Description & Location of ACM	Condition
925	1941	Annual Training Enlisted Barracks	A white, friable, asbestos containing TSI is applied to hot water tanks in the building.	Good
			A friable, hand formed, asbestos containing insulation compound is applied to the fittings and a cementitious asbestos containing material is found on straight runs of pipes, located within, outside and under the building.	Good to Poor
			Non-friable assumed asbestos containing vinyl floor tiles in 12x12 inch size, and black, asbestos containing mastics are present below vinyl floor tiles.	Good
926	1941	Annual Training Enlisted Barracks	A friable, hand formed, asbestos containing insulation compound is applied to the fittings and a cementitious asbestos containing material is found on straight runs of pipes, located within, outside and under the building.	Good to Poor
			Non-friable assumed asbestos containing vinyl floor tiles in 12x12 inch size, and black, asbestos containing mastics are present below vinyl floor tiles.	Good
927	1943	Annual Training Enlisted Barracks	A friable, hand formed, asbestos containing insulation compound is applied to the fittings and a cementitious asbestos containing material is found on straight runs of pipes, located within, outside and under the building.	Good to Poor
			Non-friable assumed asbestos containing vinyl floor tiles in 12x12 inch size, and black, asbestos containing mastics are present below vinyl floor tiles.	Good

Table 7-1
Findings of Suitability to Transfer
First CERFA Parcel Transfer
Summary of Asbestos Containing Building Survey
Fort McClellan, Alabama

Page 5 of 6

Building Number	Year Built	Description	Description & Location of ACM	Condition
954	1941	General Installation Building	Presumed asbestos containing 12x12-inch floor tile and mastic is found in the building.	Good
959	1941	General Installation Building	Presumed asbestos containing 12x12-inch floor tile and mastic is found in the building.	Good
992	1941	Recreation Center	Non-friable presumed asbestos containing 12x12 inch vinyl floor tile and mastics.	Good
1602	1979	Company Headquarters Building	Non-friable presumed asbestos containing 12x12 inch vinyl floor tile and mastics in the building.	Good
1898	1941	Storage Group Installation	Non-friable presumed asbestos containing 9x9-inch vinyl floor tile and mastics in the building.	Good
1928	1977	Bowling Center	Non-friable presumed asbestos containing 12x12 inch vinyl floor tile and mastics.	Good
1966	1976	Post Office Main	Non-friable presumed asbestos containing 12x12 inch vinyl floor tile and mastics in the building.	Good
1997	1942	Storage Group Installation	Non-friable presumed asbestos containing 12x12 inch vinyl floor tile and mastics in the building.	Good
2051	1941	Administration General Purpose	Non-friable presumed asbestos containing 12x12 inch vinyl floor tile and mastics in the building.	Good
2098	1941	Recreation Equipment Checkout	Non-friable presumed asbestos containing 9x9 inch vinyl floor tile and mastics in the building.	Good
3183	1955	Printing Plant	<p>Friable, white, chalky asbestos containing insulation is applied to 3, 4, and 6 inch pipes throughout the building. A friable, brown air cell type asbestos containing pipe insulation is found on two runs of 3 inch pipe in the warehouse area. A friable, gray and white, asbestos containing pipe fitting insulation is found applied to 3 inch pipes in the building.</p> <p>Non-friable presumed asbestos containing 12x12 inch vinyl floor tile and black, suspect mastic is present below all vinyl floor tiles in the building.</p>	<p>Good</p> <p>Good</p>
3278	1953	Company Headquarters Building	Non-friable presumed asbestos containing 9x9 and 12 x12 inch	Good

Table 7-1
Findings of Suitability to Transfer
First CERFA Parcel Transfer
Summary of Asbestos Containing Building Survey
Fort McClellan, Alabama

Page 6 of 6

Building Number	Year Built	Description	Description & Location of ACM	Condition
			vinyl floor tile and mastic.	
3298	1953	Vehicle Maintenance Shop	Friable, white, cementitious asbestos containing insulation is found on piping located in the mechanical rooms of the building.	Poor
3299	1953	Vehicle Maintenance Shop	Friable, white, cementitious asbestos containing insulation is found on piping located in the mechanical rooms of the building.	Poor
4434	1952	Scale House	Non-friable presumed asbestos containing 12x12 inch vinyl floor tile and mastics.	Good